


1

Pour some thinner on a dry cloth.



2

Rub the cloth with thinner over the peeling top layer to remove it completely.
The top layer is completely removed when the shiny base appears.

